

# BAS 1000 Bend Angle Station



Making your work easy



573 Route 30, Imperial, Pennsylvania



Tel: 724-695-2829




e-mail: [support@cs-technologies.com](mailto:support@cs-technologies.com)  
web page: [www.cs-technologies.com](http://www.cs-technologies.com)



The crimp process can create terminal twist and or bending resulting in connector mating issues. These parameters must be controlled at the crimp process.



- Microscope
- USB camera
- PC
- Work table
- Measurement software
- Fixture



Bend Angle measurements



Parallelism measurements



Bend Angle fixture



Querétaro, México: Alejandro Montelongo  
[amontelongo@cs-technologies.com](mailto:amontelongo@cs-technologies.com)  
Mobile: (521) 442 -322-3917

Chihuahua, México: José Cazares  
[jcazares@cs-technologies.com](mailto:jcazares@cs-technologies.com)  
Mobile: (521) 656-626-6188

Juárez, México: Carlos Torres  
[ctorres@cs-technologies.com](mailto:ctorres@cs-technologies.com)  
Mobile: (521) 656-638-9502